Drilling Parameters

Mud Type	WBM
Mud Density	1.10
Fluid Loss	4.0
Rheology Temperature	45.0
Plastic Viscosity	17.0
Yield Point	10.0
Filtrate Chlorides	47,000
Mud Salinity as NaCl	4.7
Filter Cake Thickness	1.0
Filtrate pH	9.0
Filtrate Potassium	1,500
Filtrate Calcium	400
Filtrate Magnesium	200
Filtrate Sulphates	1,000
Filtrate Alkalinity Mud	0.30
Filtrate Alkalinity Pm	0.70
Filtrate Alkalinity Pf	0.20
Mud Gels 10 Sec	5.0
Mud Gels 10 Min	7.0
Mud Gels 30 Min	9.0
Solids	6.0
Sand	0.3
Water	94.0
Oil	0.0
Mud Additives for Environmental Barite	0.0
Hydrogen Sulphide Gas	0.0
Carbon Dioxide Gas	0.0

Bulk Density

Bulk Density	2.65
Bulk Density Maximum	2.65
Bulk Density Minimum	2.65
Bulk Density Average	2.65

Porosity

Porosity	0.00
Porosity Maximum	0.00
Porosity Minimum	0.00
Porosity Average	0.00

Permeability

Permeability	0.00
Permeability Maximum	0.00
Permeability Minimum	0.00
Permeability Average	0.00

Saturation

Water Saturation	1.00
Water Saturation Maximum	1.00
Water Saturation Minimum	1.00
Water Saturation Average	1.00
Hydrocarbon Saturation	0.00
Hydrocarbon Saturation Maximum	0.00
Hydrocarbon Saturation Minimum	0.00
Hydrocarbon Saturation Average	0.00

Gas Ratios

Gas Ratio C1/C2	0.0
Gas Ratio C1/C3	0.0
Gas Ratio C1/C4	0.0
Gas Ratio C1/C5	0.0
Gas Ratio C1/(C2+C3)	0.0
Gas Ratio C1/(C2+C3+C4+C5)	0.0
Gas Ratio C1/(C2+C3+C4+C5+C6)	0.0
Gas Ratio C1/(C2+C3+C4+C5+C6+C7)	0.0
Gas Ratio C1/(C2+C3+C4+C5+C6+C7+C8)	0.0
Gas Ratio C1/(C2+C3+C4+C5+C6+C7+C8+C9)	0.0
Gas Ratio C1/(C2+C3+C4+C5+C6+C7+C8+C9+C10)	0.0

Gas Ratios

Gas Ratio C2/C3	0.0
Gas Ratio C2/C4	0.0
Gas Ratio C2/C5	0.0
Gas Ratio C2/(C3+C4+C5)	0.0
Gas Ratio C2/(C3+C4+C5+C6)	0.0
Gas Ratio C2/(C3+C4+C5+C6+C7)	0.0
Gas Ratio C2/(C3+C4+C5+C6+C7+C8)	0.0
Gas Ratio C2/(C3+C4+C5+C6+C7+C8+C9)	0.0
Gas Ratio C2/(C3+C4+C5+C6+C7+C8+C9+C10)	0.0

Gas Ratios

Gas Ratio C3/C4	0.0
Gas Ratio C3/C5	0.0
Gas Ratio C3/(C4+C5)	0.0
Gas Ratio C3/(C4+C5+C6)	0.0
Gas Ratio C3/(C4+C5+C6+C7)	0.0
Gas Ratio C3/(C4+C5+C6+C7+C8)	0.0
Gas Ratio C3/(C4+C5+C6+C7+C8+C9)	0.0
Gas Ratio C3/(C4+C5+C6+C7+C8+C9+C10)	0.0

Gas Ratios

Gas Ratio C4/C5	0.0
Gas Ratio C4/(C5+C6)	0.0
Gas Ratio C4/(C5+C6+C7)	0.0
Gas Ratio C4/(C5+C6+C7+C8)	0.0
Gas Ratio C4/(C5+C6+C7+C8+C9)	0.0
Gas Ratio C4/(C5+C6+C7+C8+C9+C10)	0.0

Gas Ratios

Gas Ratio C5/C6	0.0
Gas Ratio C5/(C6+C7)	0.0
Gas Ratio C5/(C6+C7+C8)	0.0
Gas Ratio C5/(C6+C7+C8+C9)	0.0
Gas Ratio C5/(C6+C7+C8+C9+C10)	0.0

Gas Ratios

Gas Ratio C6/C7	0.0
Gas Ratio C6/(C7+C8)	0.0
Gas Ratio C6/(C7+C8+C9)	0.0
Gas Ratio C6/(C7+C8+C9+C10)	0.0

Gas Ratios

Gas Ratio C7/C8	0.0
Gas Ratio C7/(C8+C9)	0.0
Gas Ratio C7/(C8+C9+C10)	0.0

Gas Ratios

Gas Ratio C8/C9	0.0
Gas Ratio C8/(C9+C10)	0.0

Gas Ratios

Gas Ratio C9/C10	0.0