



*Techlog Processed Interpretation

MicroScope Processed eCaliper

C0026A

6956.1 - 7393.7m (MD 1:200)

* A Mark of Schlumberger

COMPANY: JAMSTEC

WELL: C0026A

FIELD: C0019/C0026

PREFECTURE: Miyagi

COUNTRY: Japan

Date Processed: 4-Oct-2024 Date Logged: 23-Sep-2024

Job Number: JPJ-2024-006 Processed at: JPJ

Well Location: C0019/C0026

Latitude: 37° 56' 20.989" N Longitude: 143° 54' 47.844"

Elevation: KB: 0 DF: 28.50 m GL: -6898 m

FOLD HERE: The well name, location and borehole reference data were furnished by the customer.


Any interpretation, research, analysis, data, results, estimates, or recommendation furnished with the services or otherwise communicated by Schlumberger to the customer at any time in connection with the services are opinions based on inferences from measurements, empirical relationships, and/or assumptions; which, inferences, empirical relationships and/or assumptions are not infallible and with respect to which professionals in the industry may differ. Accordingly, Schlumberger cannot and does not warrant the accuracy, correctness, or completeness of any such interpretation, research, analysis, data, results, estimates, or recommendation. The customer acknowledges that it is accepting the services "as is," that Schlumberger makes no representation or warranty, express or implied, of any kind or description in respect thereto, and that such services are delivered with the explicit understanding and agreement that any action taken based on the services received shall be at its own risk and responsibility, and no claim shall be made against Schlumberger as a consequence thereof.


Svc. Order #:	Interpretation Center:	Analyst: Lingdan Xia	
Location:	Techlog Vers: 2022.2.2		


Remarks:


- This is 8.5in section drilling pass processed MicroScope eCaliper.
- Data presented is Real Time data.
- Permanent Datum: Mean Sea Level, Logging Measured from Drill Floor.
- HD_M16 is eCaliper result from MicroScope
- HD_M16 around 7203mMD-7319mMD is very high uncertainty and hard to check with UHRI image, because UHRI image is not continuous, and resistivity curves are very spike and lots despiking and linear interpolation were performed
- eCaliper is used to qualitative identification of borehole condition. The accuracy of the eCaliper is hard to guarantee.


BDM	ROP5		RES BY RT Linear
	0	100	
	HD_M16		























RPM 0 c/min 200	ROP5			RES_BX_RT_Linear 0.2 ohm.m 2000 RES_BS_RT_Linear 0.2 ohm.m 2000 RES_BM_RT_Linear 0.2 ohm.m 2000	HeatedReversed -0.28 4.84 UHRI_IMG_RT 0.15 ohm.m 5e+03
	0	m/h	100		
	6	in	16		
	6	BS	16		
eferenc (m) 1:200	GR_MI6_RT			UHRI_IMG_RT	0.15 ohm.m 5e+03
	0	gAPI	150		

COMPANY: JAMSTEC
WELL: C0026A
FIELD: C0019/C0026



FILED: C0019/C0020
PREFECTURE: Miyagi
COUNTRY: Japan



Date Logged: 23-Sep-2024
Date Processed: 4-Oct-2024
Surface Location: 37° 56' 20.989" N 143° 54' 47.844" E

Elevations: DF: 28.50 m GL: -6898 m
API Number: